ENVIRONMENTAL SERVICES REPORT TO THE BOARD OF ADJUSTMENT MEETING OF JUNE 16, 2009 REPORT BY DONNA O'CONNOR

Todd Carpenter

Side Lake, French Twnsp

The Carpenters have a Permit to Construct a trench system for 3 bedrooms, issued on 5-19-09. Replacement area has been designated to the north of the initial ISTS. Environmental Services recommends that the replacement ISTS area be maintained and not impacted in a manner that will negatively affect the installation and operation of an ISTS.

Troy Chittum

1477 Echo Trail, Ely

The Chittum residence is served by a mound system designed for 2 bedrooms installed in 1999. No replacement area was designated on the original septic permit or the current variance application. Mr. Chittum was advised to have a replacement area identified by a licensed ISTS professional. Environmental services is waiting for the documents from the ISTS designer.

Brian Barnes

9371 St. Odelia Beach Rd., Tower

The Barnes cabin is served by a mound system designed for 2 bedrooms installed in 2007. Replacement area has been designated. Environmental Services recommends that the replacement ISTS area be maintained and not impacted in a manner that will negatively affect the installation and operation of an ISTS.

Burntside Holdings

Wolf Lake Rd, Ely

Septic system areas have been identified on parcel B which are away from the existing parking lot. Environmental Services recommends that primary and replacement ISTS areas be maintained and not impacted in a manner that will negatively affect the installation and operation of an ISTS

Steve and Sue Grillo

8169 Long Lake Rd, Fayal Twnship

The Grillo home is served by the Fayal Municipal sewer system.